

Divider is made of \_\_\_\_\_ and \_\_\_\_\_.

- a) High carbon steel, Mild steel
- b) Mild steel, Alloy steel
- c) Alloy steel, Cast iron
- d) High carbon steel, Stainless steel

\_\_\_\_\_ is an example of marking tool.

- a) Micrometer
- b) Vernier Caliper
- c) Divider
- d) None of these

What is the range of a circle is drawn by a trammel?

- a) 0 to 150 mm
- b) 150 to 300 mm
- c) 150 to 500 mm
- d) All of these

The size of divider is measured from \_\_\_\_\_ to working point.

- a) Rivet Head
- b) Rivet center
- c) Pivot
- d) None of these

"The trammel is used for drawing parallel line." The statement is--

- a) True
- b) False

Divider is used for drawing \_\_\_\_\_:

- a) Straight line
- b) Parallel line
- c) Big line
- d) None of these



Caliper is made of \_\_\_\_\_.

- a) Cast iron
- b) Carbon steel
- c) Mild steel
- d) Stainless steel

The size of caliper is from the centre of rivet to \_\_\_\_\_.

- a) Leg point
- b) Pivot
- c) Leg
- d) None of these

Which is used for permanent marking?

- a) Divider
- b) Trammel
- c) Caliper
- d) Punch

Punch is made of \_\_\_\_\_.

- a) HCS
- b) MS
- c) SS
- d) All of these

Which is more accurate measuring instrument?

- a) Vernier Caliper
- b) Steel rule
- c) Divider
- d) None of these



\_\_\_\_\_ is marked by a key steel rule.

- a) Bore
- b) Hole
- c) Key way
- d) All of these

What is the standard length of a steel rule?

- a) 150 mm to 300 mm
- b) 150 mm to 600 mm
- c) 150 mm to 1200 mm
- d) None of these

Which is used to make a hole in wooden block?

- a) Hot Chisel
- b) Cold Chisel
- c) Both
- d) None of these



\_\_\_\_\_ is used to clean the drill hole.

- a) Gimlet
- b) Pucker
- c) Either
- d) None of these